

# FORMER ENGLISH STATION PROJECT MONTHLY PROGRESS REPORT

April 2024

---

**Partial Consent Order:** COWSPCB 15-001  
**UI Project Manager:** E. Boswell  
**LEP:** Marya B Mahoney - TRC

**Respondent:** United Illuminating Co. (UI)  
**Reporting Period:** April 2024

**Site Information:** Former English Station  
510/510A Grand Avenue  
New Haven, CT

## 1. Main Activities During Reporting Period:

- a. Continued preparation and review of the following Project-related documents/reports for submittal to CTDEEP:
  - i. Revised English Station First Floor and Interstitial Fill Investigation Summary Report. Revisions based on Supplemental Investigations completed in December 2021 thru February 2022 and the Boiler 13 IRM Concrete Investigations completed in February 2023.
  - ii. Revised English Station Boiler 1-12 Environmental Media Investigation Summary Report.
  - iii. Revised English Station Western Side Environmental Media Investigation Summary Report.
  - iv. English Station – Boiler #13 Interim Remedial Measures PCB Remedial Action Report.
- b. Perform required inspections of:
  - i. Erosion and sediment controls (re)approved under CT DEEP permit number GSN003422 on a monthly frequency.
  - ii. Eight Significant Environmental Hazard (*SEH*) areas on a bi-weekly frequency.

## 2. Future Activities:

- a. Waste characterization and coordination of disposal of IDW, PPE, and empty drums.
- b. Submit to CTDEEP:
  - i. Revised English Station First Floor and Interstitial Fill Investigation Summary Report. Revisions based on Supplemental Investigations completed in December 2021 thru February 2022 and the Boiler 13 IRM Concrete Investigations completed in February 2023.
  - ii. Revised English Station Boiler 1-12 Environmental Media Investigation Summary Report.
  - iii. Revised English Station Western Side Environmental Media Investigation Summary Report
  - iv. English Station – Boiler #13 Interim Remedial Measures PCB Remedial Action Report.
  - v. Revised Plans and Specifications for Phase 1 Soil Remediation.

## 3. Site Security:

- a. A faulty surveillance camera mounted on the exterior of the building was replaced.
- b. Continue to maintain the security measures put in place by, and acquired from, the current property owners and as upgraded by UI.