

FORMER ENGLISH STATION PROJECT MONTHLY PROGRESS REPORT

July 2024

Partial Consent Order: COWSPCB 15-001
UI Project Manager: E. Boswell
LEP: Marya B Mahoney - TRC

Respondent: United Illuminating Co. (UI)
Reporting Period: July 2024

Site Information: Former English Station
510/510A Grand Avenue
New Haven, CT

1. Main Activities During Reporting Period:

- a. Submitted to CTDEEP revised English Station First Floor and Interstitial Fill Investigation Summary Report on July 22, 2024. Revisions based on Supplemental Investigations completed in December 2021 through February 2022 and the Boiler 13 IRM Concrete Investigations completed in February 2023.
- b. Continued preparation and review of the following Project-related documents/reports for submittal to CTDEEP:
 - i. Revised English Station Boiler 1-12 Environmental Media Investigation Summary Report.
 - ii. Revised English Station Western Side Environmental Media Investigation Summary Report.
 - iii. English Station – Boiler #13 Interim Remedial Measures PCB Remedial Action Report.
- c. Perform required inspections of:
 - i. Erosion and sediment controls (re)approved under CT DEEP permit number GSN003422 on a monthly frequency.
 - ii. Eight Significant Environmental Hazard (*SEH*) areas on a bi-weekly frequency.

2. Future Activities:

- a. Submit to CTDEEP:
 - i. Revised English Station Boiler 1-12 Environmental Media Investigation Summary Report
 - ii. Revised English Station Western Side Environmental Media Investigation Summary Report
 - iii. English Station – Boiler #13 Interim Remedial Measures PCB Remedial Action Report
 - iv. Revised Plans and Specifications for Phase 1 Soil Remediation.

3. Site Security:

- a. One trespassing incident occurred in July 2024 and was reported to the New Haven Police Department and CT DEEP. An individual gained access to the site from the Mill River. A follow-up security inspection identified a cut lock at one of the barricaded building entrances, which was replaced and secured. Additional damage besides the lock or missing items were not identified.
- b. Two additional security cameras were installed on the west side of Parcel A to provide additional coverage.
- c. Continue to maintain the security measures put in place by, and acquired from, the current property owners and as upgraded by UI.