

# FORMER ENGLISH STATION PROJECT MONTHLY PROGRESS REPORT

January 2024

**Partial Consent Order:** COWSPCB 15-001  
**UI Project Manager:** E. Boswell  
**LEP:** Marya B Mahoney - TRC

**Respondent:** United Illuminating Co. (UI)  
**Reporting Period:** January 2024

**Site Information:** Former English Station  
510/510A Grand Avenue  
New Haven, CT

## 1. Main Activities During Reporting Period:

- a. Submitted Eastern Portion of English Station (Partial) Boiler 1-12 Area and Boiler 13/14 Area Inspection for Hazardous Building Materials Report to CTDEEP
- b. Submitted English Station – Boiler #13 Interim Remedial Measure Paved Area PCB Performance-Based Disposal Completion Report to CTDEEP with copy to USEPA.
- c. Continued preparation and review of the following Project-related documents/reports for submittal to CTDEEP:
  - i. Revised English Station First Floor and Interstitial Fill Investigation Summary Report. Revisions based on Supplemental Investigations completed in December 2021 thru February 2022 and the Boiler 13 IRM Concrete Investigations completed in February 2023.
  - ii. Revised English Station Boiler 1-12 Environmental Media Investigation Summary Report.
  - iii. Revised English Station Western Side Environmental Media Investigation Summary Report.
  - iv. English Station – Boiler #13 Interim Remedial Measures PCB Remedial Action Report.
- d. Perform required inspections of:
  - i. Erosion and sediment controls (re)approved under CT DEEP permit number GSN003422 on a monthly frequency.
  - ii. Eight Significant Environmental Hazard (*SEH*) areas on a bi-weekly frequency.

## 2. Future Activities:

- a. Continue preparation, for submittal to CT DEEP for review, of the Project-related documents/reports listed above in Section 1.c.
- b. Continue to work with CT DEEP on pending remedial action plan approvals needed to move forward with soil remediation activities at the Site.
- c. Continue work relating to alternatives for the Main Power Plant.

## 3. Site Security:

- a. Added additional signage: “Danger – Do Not Enter” bilingual signs to doors and gates on the first floor of the plant building.
- b. Perimeter fencing. The chain link fence along Grand Avenue was enhanced with barbed wire along top fence rail. Barbed and razor wire was added to the northeast area of the site along the bulkhead and fence panel that overhangs the bulkhead.
- c. A temporary chain link fence was installed across Parcel A and the paved clean corridor. The fence spans the area between the east and west bulkheads.
- d. Continue to maintain the security measures put in place by, and acquired from, the property owners and as upgraded by UI.